

## **XEROX SECURITY BULLETIN XRX05-006**

Vulnerabilities in the Xerox MicroServer Web Server could potentially permit unauthorised access.

The following software solution and self-service instructions are provided for the listed products to protect your confidential data from possible attacks through the network.

The software solution is compressed into a 581 KB zip file and can be accessed in the link following this bulletin on xerox.com / security:

[http://www.xerox.com/downloads/usa/en/c/cert\\_P22\\_NIAP\\_WCP\\_C\\_Only.zip](http://www.xerox.com/downloads/usa/en/c/cert_P22_NIAP_WCP_C_Only.zip)

### **Background**

There are multiple vulnerabilities in the web server code that could allow unauthorised access to the web server including:

- Vulnerabilities that could bypass authentication.
- Specially constructed HTTP requests can cause denial of service or allow unauthorised file access on an attacked machine.
- Cross-site scripting allowing contents of web pages to be modified in an unauthorised manner.

If successful, an attacker could make unauthorised changes to the system configuration. Customer and user passwords are not exposed.

**Note: This patch applies only to the products listed below.**

### **Products Affected:**

#### **WorkCentre® Pro**

C2128

C2636

C3545

## Solution

### MicroServer Web Server Patch Edited: 21-June-05

There is a patch available that fixes vulnerabilities in the Xerox MicroServer Web Server that has been identified on WorkCentre C2128/2636/3545 Multifunction Devices (MFD). The patch software only needs to be applied to the MFD if the System Software version of your MFD falls within the range listed.

You must download the patch. The patch is packaged in a ZIP format. Download the ZIP file from the URL provided and extract all contents to your desktop. **DO NOT TRY TO OPEN THE FILE WITH THE .TGZ EXTENSION.** This is the patch and must be loaded on the MFD as is.

### Install Instructions

Patch file name: **P22\_niap\_wcp\_c.tgz**

This patch is only needed if your WorkCentre falls within the following System Software versions:

**WorkCentre Pro Color 2128/2636/3545 version 0.001.04.044 through 0.001.04.505**

**If your device has a higher System Software version, then you do not need to install the patch.**

### **Confirm your System Software Version**

To determine your System Software version, you can either print a Configuration Report or view the version on the Web client interface.

To print a configuration report from the local User Interface at the machine:

- 1) Press the Machine Status button
- 2) Select Print Configuration Report
- 3) Look for the System Software Version number

To view the version from the web client interface:

- 1) Open a web browser and connect to the multifunction device by entering the IP number of the device
- 2) Select the "Index" icon in the upper middle portion of the screen
- 3) Select "Configuration".
- 4) Scroll to "Printer Setup" location that displays the System Software Version.

### **Install the Patch**

**DO NOT TRY TO OPEN THE PATCH AS IT MAY DAMAGE THE FILE.**

This patch can be submitted one of two ways for this model.

- 1) LPR Method
- 2) Machine Software (Upgrade) Method

### **LPR Method from a Windows NT, 2000, or XP**

This method requires that LPR Protocol be enabled on the device. Check the configuration report to see if the protocol is enabled. This protocol can be enabled via the Local User Interface or via the Web Interface. See Appendix A for instructions.

- 1) Open a "DOS Command Prompt". You can do this by selecting the Windows "Start" icon, and selecting "Run". Type "cmd" and select <Enter>.
- 2) Submit the patch file via the command line: **lpr -S <printer\_ip> -Pip P22\_NIAP\_WCP\_C Only.tgz**
- 3) The WorkCentre will automatically reboot in order to install the patch.
- 4) The patch is installed when **.P22** is appended to the Network Controller version number.

## Machine Software (Upgrade) Method

- 1) Open a web browser and connect to the multifunction device by entering the IP number of the device.
- 2) Select the "Index" icon in the upper middle portion of the screen.
- 3) Select "Machine Software (Upgrades)".
- 4) Enter the User Name, Admin, and the Admin Password of the device.
- 5) Under "Manual Upgrade" select Browse button to find and select the file, **P22\_NIAP\_WCP\_C Only.tgz**
- 6) Select the "Install Software" button.
- 7) The WorkCentre will automatically reboot in order to install the patch.
- 8) The patch is installed when **.P22** is appended to the Network Controller version number.

## Disclaimer

The information in this Xerox Product Response is provided "as is" without warranty of any kind. Xerox Corporation disclaims all warranties, either express or implied, including the warranties of merchantability and fitness for a particular purpose. In no event shall Xerox Corporation be liable for any damages whatsoever resulting from user's use or disregard of the information provided in this Xerox Product Response including direct, indirect, incidental, consequential, loss of business profits or special damages, even if Xerox Corporation has been advised of the possibility of such damages. Some states do not allow the exclusion or limitation of liability for consequential damages so the foregoing limitation may not apply.